U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT ESI-PRP Removal - Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region V

Subject: POLREP #20

1.

Progress

ESI-PRP Removal

B5YS

Indianapolis, IN

Latitude: 39.9128600 Longitude: -86.2423680

To: Sue Michael, City of Indianapolis

Tom White, City of Indianapolis

Harry Atkinson, IDEM Ryan Groves, IDEM Megan Nagle, IDEM George Richotte, IDEM

Jason Doerflein, Marion County Health Department

Stephen Jones, Pike Fire Department

Linda Nachowicz, U.S. EPA Region V, ERB 2

Charles Gebien, U.S. EPA Region V John Maritote, U.S. EPA Region V Janet Pope, U.S. EPA Region V

Debbie Keating, U.S. EPA Region V, ESS Karen Kirchner, U.S. EPA Region V, LCD Kendall Moore, U.S. EPA Region V, LCD Susan Perdomo, U.S. EPA Region V, ORC Gary Prichard, U.S. EPA Region V, ORC John Steketee, U.S. EPA Region V, ORC Carol Staniec, U.S. EPA Region V, Water

Kim Cussen, United Water

Nola Hicks, U.S. EPA Region V, ORC

Mark Johnson, ATSDR

Robert Darnell, U.S. Department of Justice

Stan Rigney, IDEM Randy Braun, IDEM USCG NRC, NRC

David Chung, U.S. EPA HQ

Jeff Kelley, U.S. EPA Maupin Natalie, IDEM

Eric Kaufman, Marion County Health Department

Jason Sewell, IDEM

Carol Ropski, U.S. EPA Region V, ESS

Jason Ravenscroft, Marion County Health Department

US EPA RECORDS CENTER REGION 5

Sherry Fielding, U.S. EPA HQ

Dan Sparks, USFWS Ed Karecki, USFWS Bob Masbaum, POTW

Kristen Heitman, Providence Wildlife Michael Massonne, City of Indianapolis Cheryl Carlson, Citizens Energy Group

Emily Mack, City of Indianapolis

From:

Verneta Simon & Anita L. Boseman, On-Scene Coordinators

Date:

9/12/2011

Reporting Period: 9/6/2011 - 9/9/2011

1. Introduction

1.1 Background

B5YS **Contract Number:** Site Number:

D.O. Number: **Action Memo Date:** 9/30/2010 PRP Oversight **Response Authority: CERCLA** Response Type:

Response Lead: PRP

Incident Category: Removal Action

NPL Status: Non NPL **Operable Unit:**

Mobilization Date: 4/6/2011 **Start Date:** 4/6/2011

Demob Date:

Completion Date:

CERCLIS ID: INN0051050501 **RCRIS ID:**

ERNS No.: **State Notification:**

FPN#: Reimbursable Account #:

1.1.1 Incident Category

Bankrupt Commercial Used Oils Facility

1.1.2 Site Description

See POLREP 1

1.1.2.1 Location

4910 West 86th Street, Indianapolis, Indiana 46268

2. Current Activities

2.1 Operations Section

2.1.1 Narrative See POLREP 1

2.1.2 Response Actions to Date

On September 6, 2011, Midwest had (2) 50,000 pound loads of wood pulp solidification agent delivered

- Midwest continued solidifying material in the solidification pits with wood pulp.
- Midwest continued API sump pit cleaning

On September 7, 2011, Midwest hauled off (2) 20 cyd roll-off boxes of solidified sludge to Southside Landfill

in Indianapolis, IN

- Midwest continued solidifying material in the solidification pits with wood pulp.
- Midwest pressure washed the equipment scheduled for pickup by Aaron Equipment/Wendt on September 8, 2011
- Midwest continued API sump pit cleaning
- Midwest had (2) 50,000 pound loads of wood pulp solidification agent delivered

On September 8, 2011, Midwest hauled off (4) 20 cyd roll-off boxes of solidified sludge to Southside Landfill in Indianapolis. IN

- Midwest continued solidifying material in the solidification pits with wood pulp
- Wendt was on site and removed the Aaron Equipment items for repossession
- Midwest continued API sump pit cleaning
- Midwest had (2) 50,000 pound loads of wood pulp solidification agent delivered.

On September 9, 2011, Midwest hauled off (3) 20 cyd roll-off boxes of solidified sludge to Southside Landfill in Indianapolis, IN

- Midwest continued solidifying material in the solidification pits with wood pulp.
- Roger Ward Engineering was on site for another site walk for post removal action stormwater management planning
 - Roger Ward Engineering, the City of Indianapolis, and Trihydro will be meeting at City
 Hall on September 14, 2011 at 3 30pm
- Midwest completed API sump pit cleaning
 - START, Trihydro, and Midwest agreed to conduct the visual inspection of the 12-ft deep pit on Semptember 12, 2011
- Midwest had (2) 50,000 pound loads of wood pulp solidification agent delivered
- U.S. EPA, START, and PRP Group personnel had a status update conference call regarding site schedule, planned approach for various site activities, and the Work Plan approval letter dated August 11, 2011

A map of the Site produced by START shows the Trihydro cleanup progress by tank and pit and is available in the documents section

The wood pulp solidification material is a reclaimed/recycled product. As of September 9, 2011, approximately 1,100,000 pounds had been used to solidify waste sludge.

2.1.3 Enforcement Activities, Identity of Potentially

Responsible Parties (PRPs)

N/A

2.1.4 Progress Metrics

Waste Stream	Medium	Quantity	Discharge	Treatment	Disposal
Oily Water	Liquid	3,121,734 gallons		x	
Stormwater	Liquid	424,956 gallons		x	
Tank 51 Containment	Liquid	335,120 gallons		х	
Totes and Drums	Liquid	3,885 gallons		х	

Solidified Sludge	Solid	1,120 cyd		 x
Treated Stormwater	Lıquıd	21,735 gallons	x	

2.2 Planning Section

2.2.1 Anticipated Activities

• Pilot test for bunker tank removal activities.

2.2.1.1 Planned Response Activities

None

2.2.1.2 Next Steps

US EPA will provide oversight of PRP Group removal activities.

Begin cleaning out the east containment and containment south of the Solids Building (containing Tanks 4 & 12-15).

2.2.2 Issues

Starting in Mid-July, the weather became very hot and humid, and special care was taken to make sure that people working outside are well hydrated and taking adequate breaks

Groundwater infiltration is suspected in the sanitary sewer system on Site. TriHydro is investigating potential options for mitigating infiltration.

Standing water has been observed in several locations around the site. Warmer weather can lead to mosquito breeding in standing water. EPA has requested that Trihydro address all standing water on site as soon as possible.

Ongoing management of wildlife at the site due to nearby ecosystems.

In previous POLREPs an incorrect name was used when referring to the oily water disposal facility. The correct name should be United Waste Water, Inc. not United Water.

"Control structure" refers to the pit or sump attached to and immediately south of the million gallon bunker tanks. It has been referred to as "access pit" and "access pit/control structure" in the past.

2.3 Logistics Section

Not applicable.

2.4 Finance Section

2.4.1 Narrative

Not applicable.

2.5 Safety Officer

Not applicable.

2.6 Liaison Officer

Not applicable.

2.7 Information Officer

2.7.1 Public Information Officer

2.7.2 Community Involvement Coordinator

A date has not been selected for the next community meeting.

3. Participating Entities

3.1 Unified Command

Indiana Department of Environmental Management Indianapolis Department of Public Works Pike Township Fire Department City of Indianapolis

3.2 Cooperating and Assisting Agencies

Marion County Health Department

4. Personnel On Site

U.S. EPA START Contractor

5. Definition of Terms

ASAOC – Administrative Settlement Agreement on Consent ERRS – Emergency and Rapid Response Services IDEM – Indiana Department of Environmental Management OSC – On-Scene Coordinator POLREP – Pollution Report PRP - Potentially Responsible Party RCRA – Resource Conservation and Recovery Act START – Superfund Technical Assessment and Response Team U S EPA – United States Environmental Protection Agency

6. Additional sources of information

6.1 Internet location of additional information/reports

For additional information, please refer to the US EPA lead removal action website at www epaosc org/esi

6.2 Reporting Schedule

The next POLREP will be submitted at a date to be determined.

7. Situational Reference Materials

For additional information, please refer to the documents section at www epaose org/est





